

VCDS  
Windows Based VAG/VAS Emulator  
Version: Release 10.6.3  
www.Ross-Tech.com

Dealer/Shop Name: Aes  
Workshop Code: 653 00001

Diagnostic Trouble Code Report  
Saturday, 14, July, 2012, 17:31:05:36285

VIN: WVWZZZ5ZZ80001200 License Plate:  
Mileage: 30360km-18864mi Repair Order: dj535wj-luglio-2012

Control Module Part Number: 03D 906 023 B  
Component and/or Version: SIMOS91 1.2I 2V 1413  
Software Coding: 0000071  
Work Shop Code: WSC 00000 785 00200

3 Faults Found:

- 16514 - Can't Decode, CODE File Not Loaded!  
P0130 - 009 - Can't Decode, CODE File Not Loaded! - Intermittent - MIL ON  
Freeze Frame:  
RPM: 1536 /min  
Mass Air / Rev.: 130.8 mg/str  
Voltage: 0.420 V  
Temperature: 49.5°C
- 17978 - Can't Decode, CODE File Not Loaded!  
P1570 - 008 - Can't Decode, CODE File Not Loaded! - Intermittent  
Freeze Frame:  
RPM: 1504 /min  
Temperature: 31.5°C  
Voltage: 11.42 V  
Bin. Bits: 00010000
- 16556 - Can't Decode, CODE File Not Loaded!  
P0172 - 007 - Can't Decode, CODE File Not Loaded! - Intermittent  
Freeze Frame:  
Voltage: 0.940 V  
Voltage: 0.980 V  
Lambda: 0.0 %  
Bin. Bits: 00000100

Readiness: N/A