


**About.com**

## How to Get a Medical Job

Learn how to break the process down into manageable steps, so you can obtain a profitable medical career.

[LEARN MORE](#)

## About.com Auto Repair

[Share](#)
[Print](#)

### OBD-II Codes P1000 - P1099

P1000	Transmission Solenoid Malfunction - OBD II Test Incomplete (Mazda)
P1000	Monitor Testing Not Complete (Ford)
P1001	KOER Not Able To Complete, KOER Aborted (Ford)
P1083	Fuel Control Mixture Lean (Bank 1 Sensor 1) (BMW)
P1084	Fuel Control Mixture Rich (Bank 1 Sensor 1) (BMW)
P1085	Fuel Control Mixture Lean (Bank 2 Sensor 1)
P1086	Fuel Control Mixture Rich (Bank 2 Sensor 1) (BMW)
P1087	O2 Sensor Circuit Slow Response in Lean Control Range (Bank 1 Sensor 1) (BMW)
P1088	O2 Sensor Circuit Slow Response in Rich Control Range (Bank 1 Sensor 1) (BMW)
P1089	O2 Sensor Circuit Slow Response in Lean Control Range (Bank 1 Sensor 2) (BMW)
P1090	Pre-Catalyst Fuel Trim Too Lean Bank 1 (BMW)
P1091	Pre-Catalyst Fuel Trim Too Rich Bank 1 (BMW)
P1092	Pre-Catalyst Fuel Trim Too Lean Bank 2 (BMW)
P1093	Pre-Catalyst Fuel Trim Too Rich Bank 2 (BMW)
P1094	O2 Sensor Circuit Slow Response in Rich Control Range (Bank 2 Sensor 1) (BMW)
P1095	O2 Sensor Circuit Slow Switching From Lean to Rich (Bank 1 Sensor 1) (BMW)
P1096	O2 Sensor Circuit Slow Switching From Lean to Rich (Bank 2 Sensor 1) (BMW)
P1097	O2 Sensor Circuit Slow Response after Coast Down Fuel Cutoff (Bank 1 Sensor 1) (BMW)
P1098	O2 Sensor Circuit Slow Response after Coast Down Fuel Cutoff (Bank 2 Sensor 2) (BMW)

[Back To Index](#)