

Search

Search



- Home
- Brock Archer
- Services
  - Schedule A Course
  - Upcoming Courses
  - Services for Auto Industry
- Resources
  - Emergency Response Guides
  - Extrication Pictures
  - Presentations
  - Videos
- Contact Us
- Training Notes
- New In The Auto Industry
- Stuff

« Denver, CO – Extrication – Train the Trainer – Brock Archer & Ron Moore

Where's the Boron? »

Jan 04

## Service / Safety-Emergency Disconnects

Categories:

**Training Notes** 

by Brock




There are several ways to shut down the <u>high voltage</u> (outside of the battery) in hybrid and electric vehicles. In an article to be released next week, I will cover the various <u>safety systems</u> within the vehicle that "should" shut down the high voltage and thoroughly explain the various safety, emergency and service disconnects that can be used by rescuers to isolate the high voltage to the battery.

In this training I will show the various locations where we can expect to <u>find service</u> and safety / emergency shut offs that can be used to isolate the power.

Although there are reference manuals, erg's and programs like <u>CRS</u> that can help us quickly locate these components, I hope that this writing will <u>help agencies</u> without these resources.

Here are a few of the locations where we may find the Safety or Emergency cables / disconnects

**Smart Car / 2012 – 2014** 







(Above) The  $\underline{Smart\ Car}$  – In the first image I have circled the

disconnect on the left side of the steering wheel. This is an uncommon location for a disconnect. In this case the orange plug is removed from the receptacle.

**Tesla Model S / 2012-2014** 








(Above) The Tesla Model S – In the first image I have

circled the location of the disconnect. In this case the orange cable is cut to isolate the high voltage. When using the cable type disconnect, be sure to double cut the cable to avoid accidental re-connection.

BMW Active E - 2012 - 2014






# Service/Emergency disconnect switch




(Above) BMW Active E-In the <u>first picture</u> I have circled

the location of the disconnect. In this case the orange plug is removed from it's receptacle. In this case the orange plug has a cap like cover that, when removed will isolate the power to the battery.

## Buick Regal EAssist – 2011 – 2014







VIN Edition: 4046. Fileversion: 1.4. Database: North America 06-Dec-2013-01.


#### Service/Emergency disconnect switch



(Above) Buick Regal EAssist – In the first picture I have

circled the locations of the disconnects. In this case the manufacturer is recommending that the emergency cable and the 12V battery cable both be cut for shutdown. As rescuers we know to always follow this guidance and cut the 12V battery cables as common practice at every incident.

**Chevy Volt – 2010 – 2014** 






Chevrolet - Volt - Voltec - 5dr hatchback - 2010-2014

VIN Edition: 4046. Fileversion: 1.7. Database: North America 06-Dec-2013-01.

## Service/Emergency disconnect switch






(Above) Chevy Volt – In the first picture I have circled the

location of the disconnect. In this case the basket is removed from the center console and the Orange component is removed by depressing the bottom on the bottom of the side while the entire unit is lifted.

**Chevy Tahoe – 2008 – 2014** 







(Above) <u>Chevy Tahoe</u> – In the first picture I have circled

the location of the disconnect. In this case the upholstery on the side of the back seat is stripped away to locate the disconnect. The Orange disconnect is then removed by lifting the handle up, down then out. This is a very common location for the disconnect on a SUV type of hybrid.


#### **Ford Fusion – 2013 2014**






(Above) Ford Fusion – In the first picture I have circled the location of the disconnect. In this case the disconnect would be very challenging to access if the rear seat back was in the upright position

Nissan Leaf - 2010 2014





(Above) Nissan Leaf – In the first picture I have circled the location

of the disconnect. In this case the upholstery in the center

Like {108

8+1 0

Tweet 4

This post has no tag

#### Join Our Newsletter

Name

E-mail

Subscribe

#### **Extrication Links**

- Boron Extrication
- RTC Rescue
- Scene of the Accident
- University of Extrication

#### **Posts**

- Instructor Training Program Everywhere!
- Bring Advanced Extrication to Your Department
- Where's the Boron?
- Service / Safety-Emergency Disconnects
- Denver, CO Extrication Train the Trainer Brock Archer & Ron Moore

#### **Categories**

- Airbags
- Events
- New In The Auto Industry
- Training Notes
- Uncategorized

### Copyright

- © 2014 Advanced Extrication.
  - Returns / Cancellations and Other Legal Stuff
  - Privacy Statement
  - Return to top

Powered by WordPress and the Graphene Theme.