

VCDS  
Windows Based VAG/VAS Emulator  
VCDS Version: Release 10.6.3 Data version: 20101206  
www.Ross-Tech.com

Dealer/Shop Name: Volkswagen S.p.a.  
Workshop Code: 264 00000

Self-Diagnosis Log  
Thursday,07,November,2013,21:37:48:36285

VIN: License Plate:  
Mileage: Repair Order:

Chassis Type: 9N - VW Polo  
Scan: 01 02 03 08 09 15 17 19 25 37 44 45 46 56 76

VIN: WVWZZZ9NZ3D078258 Mileage: 108570km/67462miles

-----  
Address 01: Engine Labels: Redir Fail!  
Part No: 03D 906 032 C  
Component: 1,2l/2V SIMOS3 00HS2501  
Coding: 00071  
Shop #: WSC 31414  
VCID: 1E37AF153AB  
WVWZZZ9NZ3D078258 VWZ7Z0B5908941

1 Fault Found:  
18044 - Powertrain Data Bus: Missing Message from Airbag Controller  
P1636 - 35-00 - -  
Readiness: 0010 0101

-----  
Address 03: ABS Brakes Labels: 6Q0-907-37x-ABS2.lbl  
Part No: 6Q0 907 379 L  
Component: ABS FRONT MK60 0101  
Coding: 0001097  
Shop #: WSC 31414 000 00000  
VCID: 46872775C2B

No fault code found.

-----  
Address 08: Auto HVAC Labels: 6Q0-820-045.lbl  
Part No: 6Q0 820 045  
Component: Klimaanlage X0840  
VCID: EADF33C5363

2 Faults Found:  
01596 - Motor for Outside/Recirculated Air Flap (V154)  
30-00 - Open or Short to Plus  
01596 - Motor for Outside/Recirculated Air Flap (V154)  
55-00 - Adaptation Not Successful  
-----

VCDS  
Self-Diagnosis Log  
Thursday, 07, November, 2013, 21:37:48:36285  
Page 2

VIN:   License Plate:

Address 09: Cent. Elect.      Labels: 6Qx-937-049-C.lbl  
Part No: 6Q1 937 049 C  
Component: 00 BN-SG.        1S32  
Coding: 09358  
Shop #: WSC 31414  
VCID: 3B714681899

2 Faults Found:

01321 - Control Module for Airbags (J234)  
49-00 - No Communications  
00903 - Fuse for Heated Outside Mirrors (S196)  
37-00 - Faulty

---

Address 17: Instruments      Labels: 6Q0-920-xxx-17.lbl  
Part No: 6Q0 920 800 P  
Component: KOMBI+WEGFAHRSP VDO V13  
Coding: 01131  
Shop #: WSC 00000  
VCID: 3A7F4385863  
WVWZZZ9NZ3D078258   VWZ7Z0B5908941

1 Fault Found:

01309 - Power Steering Control Module (J500)  
49-10 - No Communications - Intermittent

---

Address 19: CAN Gateway      Labels: 6N0-909-901-19.lbl  
Part No: 6N0 909 901  
Component: 02 GATEWAY CAN   1S32  
Coding: 00010  
Shop #: WSC 31414  
VCID: F0EB21AD10F

1 Fault Found:

01321 - Control Module for Airbags (J234)  
49-00 - No Communications

---

Address 44: Steering Assist    Labels: 6Q0-423-156.lbl  
Part No: 6Q0 423 156 L  
Component: LenkhilfeKYO      V910  
Coding: 00140  
Shop #: WSC 31414  
VCID: 387B598DB8F

1 Fault Found:

01321 - Control Module for Airbags (J234)  
49-00 - No Communications

---

VCDS  
Self-Diagnosis Log  
Thursday,07,November,2013,21:37:48:36285  
Page 3

VIN:   License Plate:

Address 46: Central Conv.      Labels: 6Q0-959-433.lbl  
Part No: 6Q0 959 433 H  
Component: 1D Komfortgerät   0002  
Coding: 00019  
Shop #: WSC 31414  
VCID: 408B316DE0F

No fault code found.

End -----