



VW Radio Navigation System (RNS510)

From Ross-Tech Wiki

Contents

- 1 Coding
- 2 Adaptation

Coding

Byte 00

Radio Configuration I

- Bit 1** External CD Changer Connection active
- Bit 3** Parking Aid Monitoring inactive (Standard)

Byte 01

Sound System Correction

- 00** Sound System not installed
- 01** Volkswagen Sound System
- 02** Skoda Sound System
- 05** Dynaudio Sound System

Byte 02

Speaker Channels

- 00** Sound System (active Speakers)
- 02** 2 Speaker Channels (Front only)
- 04** 4 Speaker Channels (Front and Rear)

Byte 03

Radio Configuration II

- Bit 1** Microphone Diagnostics active (Japan/China only)

Byte 04

Treble Speaker Monitoring

- 01** Monitoring inactive
- 02** Front Monitoring active / Rear Monitoring inactive
- 04** Front and Rear Monitoring active

Byte 05

Vehicle Specific Frequency Response

- 00** Volkswagen/Skoda (all)
- 01** Seat Altea (5P)
- 02** Seat Leon (1P)
- 03** Seat Toledo (5P)

04	Seat Altea XL (5P)
Byte 06	Radio Configuration III
00	Standard/Not Relevant
Byte 07	Navigation System Configuration I
Bit 0	Multifunction Steering Wheel with Shortpress Buttons installed
Bit 1	Voice Control inactive (NOT Japan/China)
Bit 2	Speed Threshold for Destination Input active
Bit 3	Speed Threshold for Speech Destination Input active
Bit 4+5	Display Variant
Byte 08	Navigation System Configuration II
00	Standard/Not Relevant

Adaptation

Retrieved from "[http://wiki.ross-tech.com/wiki/index.php/VW_Radio_Navigation_System_\(RNS510\)](http://wiki.ross-tech.com/wiki/index.php/VW_Radio_Navigation_System_(RNS510))"

Unless otherwise noted, all content on this site is Copyright © 2000-2010 by Ross-Tech LLC. All rights reserved.

"VCDS" is a Registered Trademark of Ross-Tech, LLC.

Ross-Tech is not affiliated with the Volkswagen Group in any way.