



Choose great gifts with
our product reviews



consumersearch

Get the Perfect Gift

About.com Auto Repair

[Share](#)

[Print](#)

OBD-II Codes P1800 - P1899

P1810	TFP Valve Position Switch Circuit (GM)
P1811	Maximum Adapt and Long Shift (GM)
P1819	Internal Mode Switch - No Start / Wrong Range (GM)
P1820	Internal Mode Switch Circuit A Low (GM)
P1822	Internal Mode Switch Circuit B High (GM)
P1823	Internal Mode Switch Circuit P Low (GM)
P1825	Internal Mode Switch - Invalid Range (GM)
P1826	Internal Mode Switch Circuit C High (GM)
P1851	Implausible Signal From ABS Control Module (Volkswagen)
P1854	Drive Train CAN-Bus Inoperative (Volkswagen)
P1860	TCC PWM Solenoid Circuit Electrical (GM)
P1887	TCC Release Switch Circuit (GM)
P1899	Park / Neutral Position Switch Stuck In Park or In Gear (Chrysler, Jeep)

[Back To Index](#)